materialised

FABRIC CARE, CLEANING & MAINTENANCE

MAT 5

POLYESTER BEDSPREADS & BED RUNNERS





Wash separately at 60°c. Do not overload



Do not bleach



Tumble dry at moderate temperature, ramping down to cool



Cool iron max temp 110°c

FAILURE TO ADHERE TO THESE CLEANING GUIDELINES MAY VOID YOUR WARRANTY.